

MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

December 23, 2021 December 23, 2021 December 23, 2021 DATE: DEC 2 3 2021 D

Respectfully forwarded to HON. ARISTEO APASAN BALDOS, JR., Municipal Mayor, herein INSPECTION REPORT AND RECOMMENDATION as result of site inspection conducted by the Project Monitoring Committee (PMC) on December 23, 2021 of the following projects, to wit:

- 1. Road Rehabilitation Sitio Ramos, Pagalagala to Sitio Santol, Sta. Maria Road
- 2. Road Rehabilitation Sitio Upper Bongol, Barangay Pili
- 3. Road Rehabilitation Papandayan-Rosario Boundary to Rosario Elementary School

For your reference and guidance.



C Chairperson



#FullDevolution #LocalAutonomy #LocalEmpowerment



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

INSPECTION REPORT

Project/Location:	ROAD REHABILITATION / SITIO RAMOS, PAGALAGALA TO SITIO SANTOL, STA. MARIA
	ROAD
Contractor:	FEAJ CONSTRUCTION AND GENERAL SERVICES
Project Cost:	Php 11,355,000.00
Fund Source:	2021 GENERAL FUND - LOAN
Status:	100% (COMPLETED)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on 23rd of December, 2021 and found the same to be satisfactorily completed in accordance with the Plans and Specification of the Contract.

ENGR. BEQUARD F GABAYNO	ENGR. RHEA ANN T. CULLA
Engineer I, Municipal Engineering Office	Engineer III, Municipal Engineering Office
CECILIA L.KASILAG PMC Member MARY FRANCIS DEOCORA M. FABIE PMC Member JOELITO J. PERLAS PMC Member MELIA. RAMOS PMC Member	EINGRIDER IN, MARINA PAR EINGREEN STATE JOELF, GARIN PMOMember FERNANDO T. RODIL PMOMember ANTONIO VICTOR RI OLYMPIA PMC Member DAVIEL Q. FRUELDA PMC Chairperson



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

RECOMMENDATION

Project/Location:	ROAD REHABILITATION / SITIO RAMOS, PAGALAGALA TO SITIO SANTOL, STA. MARIA
	ROAD
Contractor:	FEAJ CONSTRUCTION AND GENERAL SERVICES
Project Cost:	Php 11,355,000.00
Fund Source:	2021 GENERAL FUND - LOAN
Status:	100% (COMPLETED)


Upon review of the inspection report and other related documents, the committee recommends the Local Chief Executive to grant the request for the Final Payment to the contractor FEAJ Construction and General Services regarding the abovementioned completed project. Reports of the Project Engineer are also an integral part and basis of this recommendation.

Issued this 23rd day of December 2021.

SILAG CECIL ember



AMOS AMEL PMQ





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION

 Project/Location:
 ROAD REHABILITATION / SITIO RAMOS, PAGALAGALA TO SITIO SANTOL, STA. MARIA ROAD

 Contractor:
 FEAJ CONSTRUCTION AND GENERAL SERVICES

 Project Cost:
 Php 11,355,000.00

 Fund Source:
 2021 GENERAL FUND - LOAN

 Status:
 100% (COMPLETED)

 Date of Site Inspection:
 December 23, 2021



Mr. Daniel Q. Fruelda, PMC Chairperson with PMC Members Ms. Amelia L. Ramos, Ms. Cecilia L. Kasilag, Mr. Joel F. Garin, Hon. Mary Francis Deocora M. Fabie, Hon. Fernando T. Rodil, Hon. Joelito J. Perlas and Hon. Antonio Victor R. Olympia together with Engr. Rhea Ann T. Culla, Engineer III and Engr. Bernard F. Gabayno, Engineer I of Municipal Engineering Office conducted Project Site Inspection assisted by PMC Secretariat



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

INSPECTION REPORT

Project/Location: Contractor: Project Cost: Fund Source: Status:

n: <u>ROAD REHABILITATION / SITIO UPPER BONGOL, BARANGAY PILI</u> <u>MARTINEZ ENTERPRISES</u> <u>Php 10,000,000.00</u> <u>2021 GENERAL FUND - LOAN</u> <u>100% (COMPLETED WITH FINDINGS)</u>

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on 23rd day of December, 2021, and found the following findings, to wit:

- PCCP blocks with transverse cracking within middle block
- PCCP blocks with transverse cracking within 1.5 meters from weakened plane joints
- Uncompacted or loose road shoulder

ENGR. RHEA ANN T. CULLA GABAYNO ENGR Engineer III, Municipal Engineering Office Engineering Office Engineer I, Mun Member PMC MARY FRANCIS DEODORA M. FABIE FERNANDO T. RODIL PMC Member lemher ANTONIO W **OLYMPIA** PMC Member PMG Membe DAI C Chairperson



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

RECOMMENDATION

Project/Location: Contractor: Project Cost: Fund Source: Status:

tion: ROAD REHABILITATION / SITIO UPPER BONGOL, BARANGAY PILI MARTINEZ ENTERPRISES Php 10,000,000.00 2021 GENERAL FUND - LOAN 100% (COMPLETED WITH FINDINGS)

Upon review of the inspection report and other related documents, the committee recommends the contractor to repair/fix the observed findings on the abovemention project before granting the request for Final Payment, to wit:

- Seal with concrete epoxy the affected PCCP blocks with transverse cracking within middle block
- Remove and replace 1/3 of the affected PCCP blocks transverse cracking within 1.5 meters from weakened plane joints
- · Compact properly the loose part of road shoulder

Issued this 23rd day of December 2021.

CECI

MARY FRANCIS DEOCORA M. FABIE **PMC Member** OELITO J. PERL RMC Membe

RODIL FERN ANTONIO V **OLYMPIA** PMC Member DA FRU Ω PM IC Chairper



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION

Project/Location:	ROAD REHABILITATION / SITIO UPPER BONGOL, BARANGAY PILI	
Contractor:	MARTINEZ ENTERPRISES	
Project Cost:	Php 10,000,000.00	
Fund Source:	2021 GENERAL FUND - LOAN	
Status:	<u>100% (COMPLETED WITH FINDINGS)</u>	
Date of Site Inspection: December 23, 2021		



Mr. Daniel Q. Fruelda, PMC Chairperson with PMC Members Ms. Amelia L. Ramos, Ms. Cecilia L. Kasilag, Mr. Joel F. Garin, Hon. Mary Francis Deocora M. Fabie, Hon. Fernando T. Rodil, Hon. Joelito J. Perlas and Hon. Antonio Victor R. Olympia together with Engr. Rhea Ann T. Culla, Engineer III and Engr. Bernard F. Gabayno, Engineer I of Municipal Engineering Office conducted Project Site Inspection assisted by PMC Secretariat



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

OBSERVED FINDINGS



PCCP blocks with transverse cracking within middle block



PCCP blocks with transverse cracking within 1.5 meters from weakened plane joints



Uncompacted or loose road shoulder



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

INSPECTION REPORT

Project/Location:

Contractor: Project Cost: Fund Source: Status: ROAD REHABILITATION / PAPANDAYAN-ROSARIO BOUNDARY TO ROSARIO ELEMENTARY SCHOOL DELROL ENTERPRISES Php 10,000,000.00 2021 GENERAL FUND - LOAN 100% (COMPLETED WITH FINDINGS)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on 23rd day of December, 2021, and found the following findings, to wit:

- PCCP block with transverse cracking within 1.5 meters from weakened plane joints
- Quality of plastering of the affected PCCP blocks with water ponding under observation prior to the release of retention fee

NT. CULLA ENGR. RHE GABAYNO ENGF Engineer III, Municipal Engineering Office Ingineering Office Engineer I, Mun MARY FRANCIS DEOCORA M. FABIE T. RODIL FERNANDO PN PMC Member amber ANTONIO VICTOR R **OLYMPIA** QELITO J. PERL PMC Member PMC Member O. FRU DAN C Chairperson PMC Member



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 23, 2021

RECOMMENDATION

Project/Location:

Contractor:

Status:

Project Cost: Fund Source: n: <u>ROAD REHABILITATION / PAPANDAYAN-ROSARIO BOUNDARY TO ROSARIO</u> <u>ELEMENTARY SCHOOL</u> <u>DELROL ENTERPRISES</u> <u>Php 10,000,000.00</u> <u>2021 GENERAL FUND - LOAN</u> <u>100% (COMPLETED WITH FINDINGS)</u>

Upon review of the inspection report and other related documents and based on the latest information from the Municipal Engineering Office, the committee recommends the Local Chief Executive to only grant the request for the Full Payment to the contractor Delrol Enterprises for the abovementioned project once they repair/fix the following observed findings from the previous inspection report of the PMC, to wit:

- Remove and replace 1/3 of the affected PCCP blocks transverse cracking within 1.5 meters from weakened plane joints
- Observance of the quality of plastering of the affected PCCP blocks with water ponding prior to the release of retention fee

Issued this 23rd day of December 2021.

CECIL MARY FRANCIS DEOCORA M. FABIE FERNAM **PMC Member** ember ANTONIO VICTOR OELITO J. PERLAS OLYMPIA R PMC Member **PMC** Member AMOS Chairper



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION

Project/Location:ROAD REHABILITATION / PAPANDAYAN-ROSARIO BOUNDARY TO ROSARIO
ELEMENTARY SCHOOLContractor:DELROL ENTERPRISESProject Cost:Php 10,000,000.00Fund Source:2021 GENERAL FUND - LOANStatus:100% (COMPLETED WITH FINDINGS)Date of Site Inspection:December 23, 2021



Mr. Daniel Q. Fruelda, PMC Chairperson with PMC Members Ms. Amelia L. Ramos, Ms. Cecilia L. Kasilag, Mr. Joel F. Garin, Hon. Mary Francis Deocora M. Fabie, Hon. Fernando T. Rodil, Hon. Joelito J. Perlas and Hon. Antonio Victor R. Olympia together with Engr. Rhea Ann T. Culla, Engineer III and Engr. Bernard F. Gabayno, Engineer I of Municipal Engineering Office conducted Project Site Inspection assisted by PMC Secretariat



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

OBSERVED FINDINGS



PCCP block with transverse cracking within 1.5 meters from weakened plane joints



Quality of plastering of the affected PCCP blocks with water ponding under observation prior to the release of retention fee