

MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

RECEIVED BY :

INDORSEMENT

December 23, 2022

CRISTINE MAE G. MENORCA Administrative Aide II Date: DEC 23 2022

Respectfully forwarded to HON. ARISTEO APASAN BALDOS, JR., Municipal Mayor, herein **INSPECTION REPORT AND RECOMMENDATION** as result of site inspection conducted by the Project Monitoring Committee (PMC) on December 22, 2022 of the following projects, to wit:

- 1. Road Reblocking Guinhawa-Sta. Isabel-Buli-Pola Boundary Roads
- 2. Road Widening Along Madrid Boulevard
- 3. Construction of Emergency Operation Center Municipal Compound
- 4. Construction/Desilting/Declogging of Natural Waterways Barangays Marfrancisco, Zone I, Zone II, Zone III and Wawa
- 5. Establishment of Concrete Septic Vault for Hazardous Waste Barangay Maningcol
- 6. Construction of Level II Water System Sitio Antipolo, Barangay Del Razon
- 7. Construction of Level II Water System Sitio Center Bar, Barangay Buli

DANIEL Chairperson



#FullDevolution #LocalAutonomy #LocalEmpowerment



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

INSPECTION REPORT

 Project/Location:
 ROAD REBLOCKING / GUINHAWA-STA.ISABEL-BULI-POLA BOUNDARY ROAD

 Contractor:
 LUMEL GLENN CONSTRUCTION

 Project Cost:
 Php 34,000,000.00

 Fund Source:
 2021 GENERAL FUND - LOAN

 Status:
 100.00% (COMPLETED WITH FINDINGS)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found the following findings, to wit:

- Negative Project Slippage
- Other new findings:
 - PCCP blocks with transverse cracking acting as weakened plane joints
 - o PCCP blocks with transverse cracking within the middle block
 - PCCP blocks with longitudinal cracking
 - PCCP blocks with pockmarks
 - o PCCP blocks with on-going Remove and Replace Work
 - PCCP blocks with major scaling
 - PCCP blocks with application of concrete mixture subject for observation until the next PMC Monitoring Activities.



Engineer I, Municipal Engineering Office


PMC Member

MARY FRANCIS DEOCORA M. FABIE PMC Member



PMC Member

RAMOS AMEL



ENGR. RHEA

TI CULLA



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

 Project/Location:
 ROAD REBLOCKING / GUINHAWA-STA.ISABEL-BULI-POLA BOUNDARY ROAD

 Contractor:
 LUMEL GLENN CONSTRUCTION

 Project Cost:
 Php 34,000,000.00

 Fund Source:
 2021 GENERAL FUND - LOAN

 Status:
 100.00% (COMPLETED WITH FINDINGS)

Upon review of the inspection report and other related documents, and based on the recommendation of the Representative of the Municipal Engineering Office, the committee recommends the Local Chief Executive to deny any request for partial payment by the contractor LUMEL GLENN CONSTRUCTION due to huge slippage of the project. The contractor is hereby advised to increase their resources, manpower, equipment and materials to fast track the implementation of the project and required to follow the timeline of construction phase. The contractor is also recommended the observed findings by the committee before requesting for the final payment, to wit:

- Apply asphalt joint filler/sealant to the affected PCCP blocks with transverse cracking acting as weakened plane joints
- Seal with concrete epoxy the affected PCCP blocks with transverse cracking within middle block
- · Remove and replace the affected PCCP blocks with longitudinal cracking
- · Apply asphalt sealant to PCCP blocks with pock marks
- Finish the on-going Remove and Replace Work
- · Application of concrete mixture or remove and replace the PCCP blocks with major scaling
- Observe the condition of the PCCP blocks with applied concrete mixture subject

MARY FRANCIS DEOCORA M. FABIE RODIL FERM **PMC Member Nember JOELITO J. PERLAS** ANTONIO VICTOR OLYMPIA R PMC Member PMC Member RAMOS IC Chairpe Member



PHOTO DOCUMENTATION

Project/Location:ROAD REBLOCKING / GUINHAWA-STA.ISABEL-BULI-POLA BOUNDARY ROADContractor:LUMEL GLENN CONSTRUCTIONProject Cost:Php 34,000,000.00Fund Source:2021 GENERAL FUND - LOANStatus:100.00% (COMPLETED WITH FINDINGS)Date of Site Inspection:December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

OBSERVED FINDINGS




PCCP blocks with transverse cracking within the middle block



PCCP blocks with pockmarks





PCCP blocks with transverse cracking acting as weakened plane joints

PCCP blocks with longitudinal crackings



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE



PCCP blocks with on-going Remove and Replace Work

PCCP blocks with major scaling



PCCP blocks with application of concrete mixture subject for observation until the next PMC Monitoring Activities.



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

INSPECTION REPORT

Project/Location: Contractor: Project Cost: Fund Source: Status: ROAD WIDENING – ALONG MADRID BOULEVARD MARTINEZ ENTERPRISES Php 10,266,915.00 2022 20% DEVELOPMENT FUND 60.61% (ON-GOING)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found to be satisfactorily compliant in accordance with the Plans and Specificaiton of the Contract.

ENGR. RHEA ANN TI CULLA ENGR. 6 . GABAYNO Engineer I, Municipal Engineering Office Engineer III, Municipal Engineering Office **CECILIA L** MARY FRANCIS DEOCORA M. FABIE FERN/ NDO T. RODIL **PMC Member** Member JOELITO J. PERLA ANTONIO VICTOR R. OLYMPIA **PMC Member** PMC Member Q. FR RAMOS DAN AME PINC Chairperson Member



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

Project/Location:
Contractor:
Project Cost:
Fund Source:
Status:

ROAD WIDENING – ALONG MADRID BOULEVARD MARTINEZ ENTERPRISES Php 10,266,915.00 2022 20% DEVELOPMENT FUND 60.61% (ON-GOING)

Upon review of the inspection report and other related documents, the committee recommends the Local Chief Executive to grant the request for the Partial Payment to the contractor MARTINEZ ENTERPRISES, regarding the abovementioned project based on the **actual physical accomplishment**. Reports of the Project Engineer are also an integral part and basis of this recommendation.

MARY FRANCIS DEOCORA M. FABIE PMC Member OFI ITO PMC Member RAMOS Member






PHOTO DOCUMENTATION

Project/Location:ROAD WIDENING – ALONG MADRID BOULEVARDContractor:MARTINEZ ENTERPRISESProject Cost:Php 10,266,915.00Fund Source:2022 20% DEVELOPMENT FUNDStatus:60.61% (ON-GOING)Date of Site Inspection:December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

INSPECTION REPORT

Project/Location:	CONSTRUCTION OF EMERGENCY OPERATION CENTER / MUNICIPAL COMPOUND
Contractor:	MARTINEZ ENTERPRISES
Project Cost:	Php 12,994,981.58
Fund Source:	MDRRM FUND – TRUST FUND
Status:	<u>38.00% (ON-GOING)</u>

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found to be satisfactorily compliant in accordance with the Plans and Specification of the Contract.

ENGR. BERNARD F. GABAYNO Engineering Office Engineer I, Munici CECIL MARY FRANCIS DEDCORA M. FABIE PMC Member OELITO J. PERLAS **PMC Member** RAMOS Member

ENGR. RHEAANN T. CULLA Engineer III, Municipal Engineering Office

T. RODIL FERM ember ANTONIO VICTOR R. OLYMPIA PMC Membe DANIEL Q. FR PMC Chairperson



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

Project/Location:	CONSTRUCTION OF EMERGENCY OPERATION CENTER / MUNICIPAL COMPOUND
Contractor:	MARTINEZ ENTERPRISES
Project Cost:	Php 12,994,981.58
Fund Source:	MDRRM FUND – TRUST FUND
Status:	38.00% (ON-GOING)

Upon review of the inspection report and other related documents, the committee recommends the Local Chief Executive to grant the request for the Partial Payment, to the contractor MARTINEZ ENTERPRISES regarding the abovementioned project based on the actual physical accomplishment. Reports of the Project Engineer are also an integral part and basis of this recommendation.

CECI MARY FRANCIS DEOCORA M. FABIE FER RODIL **PMC Member** ember ANTONIO IOF PMC Membe Membe PMC RAMOS 0 **MC** Chairp lember



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION

Project/Location:CONSTRUCTION OF EMERGENCY OPERATION CENTER / MUNICIPAL COMPOUNDContractor:MARTINEZ ENTERPRISESProject Cost:Php 12,994,981.58Fund Source:MDRRM FUND – TRUST FUNDStatus:38.00% (ON-GOING)Date of Site Inspection:December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

INSPECTION REPORT

Project/Location:

Contractor: Project Cost:

Fund Source:

Status:

<u>CONSTRUCTION / DESILTING / DECLOGGING OF NATURAL WATERWAYS -</u> BARANGAYS MARFRANCISCO, ZONE I, ZONE II, ZONE III AND WAWA ORIENT STAR CONSTRUCTION, INC. Php 9,000,000.00 2021 20% DEVELOPMENT FUND 100.00% (COMPLETED)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found that all previus findings have been fixed/rectified, and the same to be satisfactorily completed in accordance with the Plans and Specification of the Contract.







RAMOS Member

ENGR. RHEA ANN T. CULLA Engineer III, Municipal Engineering Office

FER T. RODIL ember ANTONIO VICTORI/R. OLYMPIA PMC Member DANIEL Q. FR PMC Chairperson



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

Project/Location: CONSTRUCTION / DESILTING / DECLOGGING OF NATURAL WATERWAYS -BARANGAYS MARFRANCISCO, ZONE I, ZONE II, ZONE III AND WAWA Contractor: ORIENT STAR CONSTRUCTION, INC. Project Cost: Php 9,000,000.00 Fund Source: 2021 20% DEVELOPMENT FUND Status: 100.00% (COMPLETED)

Upon review of the inspection report and other related documents, the committee recommends the Local Chief Executive to grant the request for the Final Payment, to the contractor ORIENT STAR CONSTRUCTION, INC. Regarding the abovementioned project. Reports of the Project Engineer are also an integral part and basis of this recommendation.

CECIL PMC Member MARY FRANCIS DEOCORA M. FABIE T. RODIL FERN **PMC Member Member** ANTONIO JOELITO J. PERI . OLYMPIA PMC Member PMC Member RAMOS AMELIA MC Chairperso PMC Member



PHOTO DOCUMENTATION

Project/Location:	CONSTRUCTION / DESILTING / DECLOGGING OF NATURAL WATERWAYS -
	BARANGAYS MARFRANCISCO, ZONE I, ZONE II, ZONE III AND WAWA
Contractor:	ORIENT STAR CONSTRUCTION, INC.
Project Cost:	<u>Php 9,000,000.00</u>
Fund Source:	2021 20% DEVELOPMENT FUND
Status:	<u>100.00% (COMPLETED)</u>
Date of Site Inspec	tion: December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN **PROJECT MONITORING COMMITTEE**

Date: December 22, 2022

INSPECTION REPORT

Project/Location:


Contractor:

Project Cost:

Fund Source: Status: ESTABLISHMENT OF CONCRETE SEPTIC VAULT FOR HAZARDOUS WASTE / BARANGAY MANINGCOL LAS MINAS DE ORO CONSTRUCTION Php 3,000,000.00 2022 20% DEVELOPMENT FUND 92.00% (ON-GOING)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found the following findings, to wit:

- Incomplete installation of liner (2 sides)
- Disaligned gate
- Inappropriate installation of manhole cover





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

Project/Location:

Contractor:

Project Cost:

Fund Source:

Status:

ESTABLISHMENT OF CONCRETE SEPTIC VAULT FOR HAZARDOUS WASTE / BARANGAY MANINGCOL LAS MINAS DE ORO CONSTRUCTION Php 3,000,000.00 2022 20% DEVELOPMENT FUND 92.00% (ON-GOING)

Upon review of the inspection report and other related documents, the committee recommends the Local Chief Executive to **deny** the request for the Partial Payment to the contractor LAS MINAS DE ORO CONSTRUCTION regarding the abovementioned project since the project is incomplete. The contractor is also recommended to rectify/fix the observed findings of the committee before requesting for the final payment, to wit:

- Installation of liner both sides
- Align the installation of gate
- Install the manhole cover according to the design

PMC Member MARY FRANCIS DEOCORA M. FABIE RODIL FER **PMC Member** lember ANTONIO V JOELITO J. PERLAS **OLYMPIA PMC Member** PMC Member RAMOS DAN **PMC** Chairpers Member



PHOTO DOCUMENTATION

 Project/Location:
 ESTABLISHMENT OF CONCRETE SEPTIC VAULT FOR HAZARDOUS WASTE / BARANGAY MANINGCOL

 Contractor:
 LAS MINAS DE ORO CONSTRUCTION

 Project Cost:
 Php 3,000,000.00

 Fund Source:
 2022 20% DEVELOPMENT FUND

 Status:
 92.00% (ON-GOING)

 Date of Site Inspection:
 December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

OBSERVED FINDINGS



Incomplete installation of liner (2 sides)





Inappropriate installation of manhole cover

Disaligned gate



MUNICIPAL GOVERNMENT OF PINAMALAYAN **PROJECT MONITORING COMMITTEE**

Date: December 22, 2022

INSPECTION REPORT

Project/Location:	CONSTRUCTION OF LEVEL II WATER SYSTEM - SITIO ANTIPOLO, DEL RAZON
Contractor:	LAS MINAS DE ORO CONSTRUCTION
Project Cost:	Php 1,999,892.08
Fund Source:	2021 LGSF-FALGU
Status:	70.00% (ON-GOING)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found that the project has a negative slippage and considered as high-risk project. It also found out that the water test from NWRB is not yet received by the committe.

ENGR. RHEA ANN T. CULLA ENGR. DERNARD GABAYNO Engineer III, Municipal Engineering Office Engineer I, Municipal Engineering Office CECIL T. RODIL MARY FRANCIS DEOCORA M. FABIE FERN PMC Member **PMC Member** ANTONIO VICTOR R JOELITO J PMC Men be RAMOS DAN PMC Chairperson Member

YMPIA



MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

RECOMMENDATION

Project/Location:
Contractor:
Project Cost:
Fund Source:
Status:

<u>CONSTRUCTION OF LEVEL II WATER SYSTEM – SITIO ANTIPOLO, DEL RAZON</u> <u>LAS MINAS DE ORO CONSTRUCTION</u> <u>Php 1,999,892.08</u> <u>2021 LGSF-FALGU</u> <u>70.00% (ON-GOING)</u>

Upon review of the inspection report and other related documents, the committee recommends contractor to increase their resources, manpower, equipment and materials to fast track the implementation of the project since the project is considered as "high-risk project".

CEC MARY FRANCIS DEOCORA M. FABIE **PMC Member** JOELITO J. PERL PMC Member RAMOS C Member






PHOTO DOCUMENTATION

 Project/Location:
 CONSTRUCTION OF LEVEL II WATER SYSTEM – SITIO ANTIPOLO, DEL RAZON

 Contractor:
 LAS MINAS DE ORO CONSTRUCTION

 Project Cost:
 Php 1,999,892.08

 Fund Source:
 2021 LGSF-FALGU

 Status:
 70.00% (ON-GOING)

 Date of Site Inspection:
 December 22, 2022





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022

INSPECTION REPORT

Project/Location:
Contractor:
Project Cost:
Fund Source:
Status:

DN: <u>CONSTRUCTION OF LEVEL II WATER SYSTEM – SITIO CENTER BAR, BULI</u> ORIENT STAR CONSTRUCTION, INC. Php 1,992,800.00 2021 LGSF-FALGU 40.00% (ON-GOING)

We, the undersigned members of the Project Monitoring Committee and Representatives from Municipal Engineering Office with the assistance of PMC Secretariat, conducted a joint inspection of the above-stated project, on the 22nd day of December, 2022, and found that the project has a negative slippage and considered as high-risk project. It also found out that the water test from NWRB is not yet received by the committe.

ENGR RD F. GABAYNO Engineer I, Municipal Engineering Office


CECIL PMC Member



OELITO J. PERLAS PMC Member

AMEL

ENGR. RHEA A Engineer III, Municipal Engineering Office





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

Date: December 22, 2022


RECOMMENDATION

Project/Location:
Contractor:
Project Cost:
Fund Source:
Status:

<u>CONSTRUCTION OF LEVEL II WATER SYSTEM – SITIO CENTER BAR, BULI</u> ORIENT STAR CONSTRUCTION, INC. Php 1,992,800.00 2021 LGSF-FALGU 40.00% (ON-GOING)

Upon review of the inspection report and other related documents, the committee recommends contractor to increase their resources, manpower, equipment and materials to fast track the implementation of the project since the project is considered as "high-risk project".

CECILIA PMC Member MARY FRANCIS DEOCORA M. FABIE PMC Member JOELITO J. PERLAS PMC Member RAMOS Member





MUNICIPAL GOVERNMENT OF PINAMALAYAN PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION

Project/Location:CONSTRUCTION OF LEVEL II WATER SYSTEM – SITIO CENTER BAR, BULIContractor:ORIENT STAR CONSTRUCTION, INC.Project Cost:Php 1,992,800.00Fund Source:2021 LGSF-FALGUStatus:40.00% (ON-GOING)Date of Site Inspection:December 22, 2022

